



Informe Provisional

Informe Provisional

Datos del Suceso

File number	030163766/2020	
Occurrence class	Accident	
Occurrence category	F-POST: Fire/smoke (post-impact) CFIT: Controlled flight into or toward terrain	
Occurrence status	Factual	
UTC date/time	6/5/2020	01:45
State/area of occ	South America Argentina	
Location name	Esquel - Pcia. Chubut	
Latitude of occ	42:54:14 South	
Longitude of occ	71:08:08 West	

Reseña del Vuelo

" En un vuelo de aviación comercial no regular sanitario, en la aproximación final instrumental, la aeronave impactó contra el terreno, a 70 metros del borde lateral izquierdo de la pista 23, a 800 metros pasados el umbral de la cabecera."

Información del Vuelo

Last departure point	Argentina SADF : San Fernando, Ba
Planned destination	Argentina SAVE (EQS) : Esquel , Cht
Duration of flight	2,5 Hour(s)



Call sign	<i>LV-BXU</i>
Flight phase	<i>Approach</i>

Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft	3	1				4
Grand total	3	1				4

Información de la Aeronave

Aircraft registration	<i>LV-BXU</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Destroyed</i>
Manufacturer/model	<i>LEARJET 35 A</i>
Aircraft category	<i>Fixed Wing Aeroplane Large Aeroplane Large Aeroplane</i>
Year built	<i>1981</i>
Serial number	<i>462</i>
Maximum t/o mass	<i>8300 kg</i>
Mass group	<i>5 701 to 27 000 kg</i>
Total cycles a/c	<i>10473</i>
Aircraft total time	<i>11711 Hour(s)</i>
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>



Información del Motor

Engine position	1
Manufacturer/model	HONEYWELL TFE731-2/-3/-4/-5 series
Engine serial number	P-89267C
Time since new	11352,5 Hour(s)
Engine cycles	10161
Time since overhaul	1326 Hour(s)
Cycles since overhaul	1486
Time since inspection	76 Hour(s)

Información del Motor

Engine position	2
Manufacturer/model	HONEYWELL TFE731-2/-3/-4/-5 series
Engine serial number	P-89262
Time since new	11639 Hour(s)
Engine cycles	10360
Time since overhaul	783 Hour(s)
Cycles since overhaul	893
Time since inspection	76 Hour(s)

Información sobre el Personal

Age		Gender	Male
Category	Pilot-in-command		
License type	Aeroplane pilot Airline transport pilot		
License issued by	State of Registry		
Ratings	Held required rating		



Experience all a/c		Experience this a/c	1498 Hour(s)
Experience all-90 days	35 Hour(s)	Experience on a/c-90 da	35 Hour(s)
Experience all-24 hours	2 Hour(s)	Experience on a/c-24 ho	2 Hour(s)

Información sobre el Personal

Age		Gender	Male
Category	Co-pilot		
License type	Aeroplane pilot Commercial pilot		
License issued by	State of Registry		
Ratings	Held required rating		
Experience all a/c	2612 Hour(s)	Experience this a/c	
Experience all-90 days	30 Hour(s)	Experience on a/c-90 da	30 Hour(s)
Experience all-24 hours	2 Hour(s)	Experience on a/c-24 ho	2 Hour(s)

Información Meteorológica

Weather relevant	Yes
Weather conditions	IMC
Visibility	120 m
Light conditions	Night/moonlight
Wind description	Calm
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	



Información sobre el Lugar del Suceso

Wreckage location	<i>On aerodrome/airstrip</i>
Terrain type	<i>Level/flat</i>
Elevation terrain	<i>2524 ft</i>
Surface type	<i>Grass</i>
Length wreckage trail	<i>450 m</i>
Rwy exit at	<i>Left side</i>
Dist to exit	<i>800 m</i>

Información sobre los Restos de la Aeronave y el Impacto

Speed at impact	
Speed level	
Impact angle	<i>Low</i>
Pitch attitude	<i>Nose level</i>
Roll attitude	<i>Slight bank (0-30)</i>

Supervivencia

Survivability	<i>Yes</i>
Locating method	<i>ATC computer generated</i>
ELB-A, ELT status	<i>Damaged</i>
Pilot restraint system	<i>Unknown</i>
Co-pilot restraint system	<i>Unknown</i>
Escape time	<i>20 Minute(s)</i>



Información sobre el Operador

Operation type	<i>Commercial Air Transport Cargo Air Ambulance</i>
Schedule type	<i>Non-scheduled</i>
Operator	<i>Argentina Private Operator</i>
Operator type	<i>Private owner</i>

Estado de la Investigación

Investigation Progress	<i>Se recibió el 7/3/22 reporte de fabricante de motores con desgrabación de DEEC y EGPWS. Se inicia etapa de análisis, conclusión y recomendaciones.</i>
Corrective Actions / Safety Recommendations	



República Argentina - Poder Ejecutivo Nacional
Las Malvinas son argentinas

Hoja Adicional de Firmas
Informe gráfico

Número:

Referencia: LV-BXU - Informe Provisional (año 2022)

El documento fue importado por el sistema GEDO con un total de 6 pagina/s.