



Informe Provisional

Informe Provisional

Datos del Suceso

File number	60742424/21	
Occurrence class	<i>Incident</i>	
Occurrence category	<i>SCF-NP: System/component failure or malfunction [non-powerplant]</i>	
Occurrence status	<i>Factual</i>	
UTC date/time	6/7/2021	16:30
State/area of occ	<i>South America Argentina</i>	
Location name	<i>Aeropuerto Internacional San Fernando (SADF)</i>	
Latitude of occ	<i>34:27:37 South</i>	
Longitude of occ	<i>58:35:45 West</i>	

Reseña del Vuelo

En un vuelo de aviación general durante el rodaje la aeronave experimentó la rotura del tren de aterrizaje de nariz.

Información del Vuelo

Last departure point	<i>Argentina SADF : San Fernando, Ba</i>
Planned destination	<i>Argentina SASA : Salta, S.</i>
Duration of flight	<i>0 Hour(s)</i>
Call sign	<i>LV-AHX</i>
Flight phase	<i>Taxi</i>



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft				2		2
Grand total				2		2

Información de la Aeronave

Aircraft registration	<i>LV-AHX</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Minor</i>
Manufacturer/model	<i>CESSNA 560</i>
Aircraft category	<i>Fixed Wing Aeroplane Large Aeroplane</i>
Year built	<i>1982</i>
Serial number	<i>560-0090</i>
Maximum t/o mass	<i>7200 kg</i>
Mass group	<i>5 701 to 27 000 kg</i>
Total cycles a/c	<i>13225</i>
Aircraft total time	<i>10648 Hour(s)</i>
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>

Información del Motor

Engine position	<i>1</i>
Manufacturer/model	<i>PRATT & WHITNEY (CANADA) JT15 (JT15D-5A)</i>
Engine serial number	<i>PCE-108186</i>
Time since new	



Engine cycles

Time since overhaul

Cycles since overhaul

Time since inspection

Información del Motor

Engine position 2

Manufacturer/model PRATT & WHITNEY (CANADA)
JT15 (JT15D-5A)

Engine serial number PCE-108184

Time since new

Engine cycles

Time since overhaul

Cycles since overhaul

Time since inspection

Información sobre el Personal

Age 58 Year(s) **Gender** Male

Category Pilot-in-command

License type Aeroplane pilot
Airline transport pilot

License issued by State of Registry

Ratings

Experience all a/c **Experience this a/c**

Experience all-90 days **Experience on a/c-90 da**

Experience all-24 hours **Experience on a/c-24 ho**



Información sobre el Personal

Age	<i>59 Year(s)</i>	Gender	<i>Male</i>
Category	<i>Co-pilot</i>		
License type	<i>Aeroplane pilot Other</i>		
License issued by	<i>State of Registry</i>		
Ratings			
Experience all a/c		Experience this a/c	
Experience all-90 days		Experience on a/c-90 da	
Experience all-24 hours		Experience on a/c-24 ho	

Información Meteorológica

Weather relevant	<i>No</i>
Weather conditions	<i>VMC</i>
Visibility	
Light conditions	<i>Daylight</i>
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Información sobre el Lugar del Suceso

Wreckage location	<i>On aerodrome/airstrip</i>
Terrain type	<i>Level/flat</i>
Elevation terrain	<i>10 ft</i>
Surface type	<i>Pavement</i>
Length wreckage trail	



Rwy exit at

Dist to exit

Información sobre el Operador

Operation type *Non-Commercial Operations
Relocation*

Schedule type *Non-scheduled*

Operator *Argentina
Private Operator*

Operator type *Corporate/executive*

Estado de la Investigación

Investigation Progress *A la espera del análisis e informe microscópico de la mecánica de falla de la horquilla.*

**Corrective Actions /
Safety Recommendations** *Ninguna al momento de este informe.*