



Informe Provisional

Informe Provisional

Datos del Suceso

File number	109328996/21	
Occurrence class	Accident	
Occurrence category	LOLI: Loss of lifting conditions en-route CTOL: Collision with obstacle(s) during take-off and landing	
Occurrence status	Factual	
UTC date/time	10/11/2021	20:50
State/area of occ	South America Argentina	
Location name	35 kms de San Carlos de Bolivar Provincia de Buenos Aires	
Latitude of occ	36:04:50 South	
Longitude of occ	60:52:10 West	

Reseña del Vuelo

" Durante la aproximación para el aterrizaje fuera de pista, debido a la pérdida de las condiciones atmosféricas de sustentación, la aeronave impacta primeramente contra un tendido eléctrico de media tensión, causando la pérdida de sustentación y posterior impacto sobre el terreno."

Información del Vuelo

Last departure point	Argentina SAZI : Bolivar, Ba
Planned destination	Argentina SAZI : Bolivar, Ba
Duration of flight	2 Hour(s)
Call sign	LV-ENW



Flight phase	<i>Approach</i>
---------------------	-----------------

Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft		<i>1</i>				<i>1</i>
Grand total		<i>1</i>				<i>1</i>

Información de la Aeronave

Aircraft registration	<i>LV-ENW</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Minor</i>
Manufacturer/model	<i>AMS LS4</i>
Aircraft category	
Year built	
Serial number	<i>4076</i>
Maximum t/o mass	
Mass group	<i>0-2 250 kg</i>
Total cycles a/c	
Aircraft total time	
Maintenance docs	
Airworthiness cert.	



Información sobre el Personal

Age	39 Year(s)	Gender	Male
Category	Pilot-in-command		
License type	Glider pilots Private pilot		
License issued by	State of Registry		
Ratings			
Experience all a/c	560 Hour(s)	Experience this a/c	
Experience all-90 days	20 Hour(s)	Experience on a/c-90 da	
Experience all-24 hours	1 Hour(s)	Experience on a/c-24 ho	

Información Meteorológica

Weather relevant	No
Weather conditions	VMC
Visibility	
Light conditions	Daylight
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Información sobre el Lugar del Suceso

Wreckage location	Off aerodr > 10 km
Terrain type	Level/flat
Elevation terrain	295,275 ft
Surface type	Crops/cultivated field
Length wreckage trail	20 m



Rwy exit at

Dist to exit

Información sobre los Restos de la Aeronave y el Impacto

Speed at impact	<i>53,996 kt</i>
Speed level	<i>Low</i>
Impact angle	<i>Low</i>
Pitch attitude	<i>Nose level</i>
Roll attitude	<i>Wings level</i>

Supervivencia

Survivability	<i>Yes</i>
Locating method	<i>ATC computer generated</i>
ELB-A, ELT status	
Pilot restraint system	<i>Upper body restraint used</i>
Co-pilot restraint system	
Escape time	

Información sobre el Operador

Operation type	<i>Non-Commercial Operations Pleasure Other</i>
Schedule type	<i>Non-scheduled</i>
Operator	<i>Argentina Private Operator</i>
Operator type	<i>Private owner</i>



Estado de la Investigación

Investigation Progress

Se esta a la espera de la respuesta de la autoridad aeronautica respecto a el certificado de aeronavegabilidad

**Corrective Actions /
Safety Recommendations**