



Informe Preliminar

Informe Preliminar

Datos del Suceso

File number	18137028/22	
Occurrence class	Incident	
Occurrence category	SCF-NP: System/component failure or malfunction [non-powerplant]	
Occurrence status	Preliminary	
UTC date/time	24/2/2022	12:38
State/area of occ	South America Argentina	
Location name	SAEZ	
Latitude of occ	34:49:02 South	
Longitude of occ	58:32:19 West	

Reseña del Vuelo

En un vuelo de aviación comercial regular, despegando de Aeroparque Jorge Newbery con destino a Rio Gallegos, se produce una despresurización de cabina a FL 280, la tripulación realizó un descenso en emergencia hasta la altitud de seguridad, regresando al aeropuerto de Ezeiza donde aterrizaron en condiciones overweight.

Información del Vuelo

Last departure point	Argentina SABE (AEP) : Buenos Aires/Aeroparque, Jorge Newbery, Cf
Planned destination	Argentina SAWG (RGL) : Rio Gallegos, Sc
Duration of flight	1 Hour(s)
Call sign	AR 1802
Flight phase	En route



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground				0		0
Total on aircraft				105		105
Grand total				105		105

Información de la Aeronave

Aircraft registration	<i>LV-GIQ</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>None</i>
Manufacturer/model	<i>EMBRAER ERJ190 100 100IGW</i>
Aircraft category	<i>Fixed Wing Aeroplane Large Aeroplane</i>
Year built	
Serial number	<i>19000716</i>
Maximum t/o mass	<i>51800 kg</i>
Mass group	<i>27 001 to 272 000 kg</i>
Total cycles a/c	
Aircraft total time	
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>

Información sobre el Personal

Age	<i>49 Year(s)</i>	Gender	<i>Male</i>
Category	<i>Pilot-in-command</i>		
License type	<i>Aeroplane pilot Airline transport pilot</i>		
License issued by	<i>State of Registry</i>		
Ratings	<i>Held required rating</i>		
Experience all a/c		Experience this a/c	



Experience all-90 days	Experience on a/c-90 d
Experience all-24 hours	Experience on a/c-24 h

Información sobre el Personal

Age		Gender	<i>Male</i>
Category	<i>Co-pilot</i>		
License type	<i>Aeroplane pilot Airline transport pilot</i>		
License issued by	<i>State of Registry</i>		
Ratings	<i>Held required rating</i>		
Experience all a/c	<i>4300 Hour(s)</i>	Experience this a/c	
Experience all-90 days	<i>91,6 Hour(s)</i>	Experience on a/c-90 d	<i>91,6 Hour(s)</i>
Experience all-24 hours		Experience on a/c-24 h	

Información Meteorológica

Weather relevant	
Weather conditions	<i>IMC</i>
Visibility	
Light conditions	<i>Daylight</i>
Wind description	
Wind direction	
Wind speed	
Speed measured at	
Wind gusts	

Información sobre el Lugar del Suceso

Wreckage location	<i>On aerodrome/airstrip</i>
Terrain type	<i>Level/flat</i>
Elevation terrain	<i>69 ft</i>
Surface type	<i>Pavement</i>
Length wreckage trail	



Rwy exit at	<i>Left side</i>
Dist to exit	

Información sobre el Operador

Operation type	<i>Commercial Air Transport Passenger Airline</i>
Schedule type	<i>Scheduled</i>
Operator	<i>Argentina Aerolíneas Argentinas</i>
Operator type	<i>Not applicable</i>

Líneas de Investigación

Descr factor subject	<i>Aircraft and operations Aircraft components and systems 2100 Air conditioning system 2130 Pressurization control 2133 Pressure regulator valve</i>
Factors justification	

Líneas de Investigación

Descr factor subject	<i>Aircraft and operations Aircraft maintenance/repair Maintenance procedures</i>
Factors justification	