



Informe Preliminar

Informe Preliminar

Datos del Suceso

File number	39839692/23	
Occurrence class	Accident	
Occurrence category	ARC: Abnormal runway contact	
Occurrence status	Preliminary	
UTC date/time	10/4/2023	18:10
State/area of occ	South America Argentina	
Location name	LAD 2882 El Guri, Villa de María, Córdoba	
Latitude of occ	29:55:21 South	
Longitude of occ	63:33:30 West	

Reseña del Vuelo

En un vuelo privado de aviación general, durante la fase de aterrizaje, la aeronave tuvo un contacto anormal con la pista.

Información del Vuelo

Last departure point	Argentina (LAD 3029 Tancacha/FASA)
Planned destination	Argentina (LAD 2882 El Guri)
Duration of flight	1,4 Hour(s)
Call sign	LV-KGT
Flight phase	Landing



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground	0	0	0	0	0	0
Total on aircraft	0	0	0	3	0	3
Grand total	0	0	0	3	0	3

Información de la Aeronave

Aircraft registration	<i>LV-KGT</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Substantial</i>
Manufacturer/model	<i>CESSNA 182 T (Textron)</i>
Aircraft category	
Year built	<i>2021</i>
Serial number	<i>18283161</i>
Maximum t/o mass	<i>1400 kg</i>
Mass group	<i>0-2 250 kg</i>
Total cycles a/c	
Aircraft total time	<i>250 Hour(s)</i>
Maintenance docs	<i>Current</i>
Airworthiness cert.	<i>Valid</i>

Información del Motor

Engine position	<i>1</i>
Manufacturer/model	<i>LYCOMING 540 FAMILY</i>
Engine serial number	<i>L37899-48E</i>
Time since new	<i>250 Hour(s)</i>
Engine cycles	
Time since overhaul	



Cycles since overhaul
Time since inspection

Información de la Hélice

Prop position	1
Make of propeller	MCCAULEY PROPELLER SYSTEMS
Propeller model	B3D36C431C
Prop serial	210841
Time since new	250 Hour(s)
Time since overhaul	
Time since inspection	

Información sobre el Personal

Age	58 Year(s)	Gender	Male
Category	Pilot-in-command		
License type	Aeroplane pilot Private pilot		
License issued by	State of Registry		
Ratings	Held required rating		
Experience all a/c	443,7 Hour(s)	Experience this a/c	
Experience all-90 days	44,8 Hour(s)	Experience on a/c-90 d	34 Hour(s)
Experience all-24 hours		Experience on a/c-24 h	

Información Meteorológica

Weather relevant	No
Weather conditions	VMC
Visibility	
Light conditions	Daylight
Wind description	
Wind direction	
Wind speed	



Speed measured at

Wind gusts

Información sobre el Lugar del Suceso

Wreckage location *On aerodrome/airstrip*

Terrain type *Level/flat*

Elevation terrain *751 ft*

Surface type *Grass*

Length wreckage trail *88 m*

Rwy exit at

Dist to exit

Información sobre los Restos de la Aeronave y el Impacto

Speed at impact *50 kt*

Speed level *Unknown*

Impact angle *Intermediate*

Pitch attitude *Nose down*

Roll attitude *Wings level*

Supervivencia

Survivability *Yes*

Locating method

ELB-A, ELT status *Not activated*

Pilot restraint system *Upper body restraint used*

Co-pilot restraint system *Upper body restraint*

Escape time



Información sobre el Operador

Operation type	<i>Non-Commercial Operations Business</i>
Schedule type	<i>Non-scheduled</i>
Operator	<i>Argentina Private Operator</i>
Operator type	<i>Private owner</i>

Líneas de Investigación

Descr factor subject	<i>Aircraft and operations Aircraft operation Flight crew perception/judgment Height judgement</i>
Factors justification	<i>De acuerdo a la entrevista del piloto y la dinámica del impacto observada.</i>