



Informe Preliminar

Informe Preliminar

Datos del Suceso

File number	113471705/21	
Occurrence class	Accident	
Occurrence category	USOS: Undershoot/overshoot	
Occurrence status	Initial notification	
UTC date/time	20/11/2021	12:35
State/area of occ	South America Argentina	
Location name	AD Intendente Albear	
Latitude of occ	35:14:01 South	
Longitude of occ	63:33:53 West	

Reseña del Vuelo

En un vuelo privado de aviación general , el piloto al ingresar a la ATZ del aeródromo de Intendente Alvear, realizaba un reconocimiento del lugar, iniciando el circuito, confunde la pista con su lateral derecho, en una zona recientemente sembrada, aterrizando en el y capotando sobre el final de su carrera de aterrizaje.

Información del Vuelo

Last departure point	Argentina SAZG (GPO) : General Pico, Lp
Planned destination	Argentina Other (IAL: AD Intendete Alvear La Pampa)
Duration of flight	1 Hour(s)
Call sign	LV-BXJ
Flight phase	Landing



Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft				1		1
Grand total				1		1

Información de la Aeronave

Aircraft registration	<i>LV-BXJ</i>
State of registry	<i>Argentina</i>
Aircraft damage	<i>Substantial</i>
Manufacturer/model	<i>CESSNA 152</i>
Aircraft category	<i>Fixed Wing Aeroplane Small Aeroplane Very Light Aeroplane</i>
Year built	<i>1979</i>
Serial number	<i>152-83463</i>
Maximum t/o mass	<i>757,7 kg</i>
Mass group	<i>0-2 250 kg</i>
Total cycles a/c	
Aircraft total time	
Maintenance docs	
Airworthiness cert.	

Información del Motor

Engine position	<i>1</i>
Manufacturer/model	<i>LYCOMING 235 FAMILY</i>
Engine serial number	<i>L-16648-15</i>
Time since new	
Engine cycles	
Time since overhaul	



Cycles since overhaul
Time since inspection

Información de la Hélice

Prop position	1
Make of propeller	MCCAULEY PROPELLER SYSTEMS
Propeller model	1A103/TCM6958
Prop serial	773974
Time since new	
Time since overhaul	
Time since inspection	

Información sobre el Personal

Age	46 Year(s)	Gender	Male
Category	Pilot-in-command		
License type	Aeroplane pilot Private pilot		
License issued by	State of Registry		
Ratings	No required rating		
Experience all a/c	21 Hour(s)	Experience this a/c	
Experience all-90 days	3,6 Hour(s)	Experience on a/c-90 d	
Experience all-24 hours	0,5 Hour(s)	Experience on a/c-24 h	

Información Meteorológica

Weather relevant	No
Weather conditions	VMC
Visibility	
Light conditions	Daylight
Wind description	
Wind direction	
Wind speed	



Speed measured at
Wind gusts

Información sobre el Lugar del Suceso

Wreckage location	<i>On aerodrome/airstrip</i>
Terrain type	<i>Level/flat</i>
Elevation terrain	<i>127 ft</i>
Surface type	<i>Crops/cultivated field</i>
Length wreckage trail	
Rwy exit at	
Dist to exit	

Supervivencia

Survivability	<i>Yes</i>
Locating method	<i>ELB-A (ELT) only</i>
ELB-A, ELT status	<i>Operated effectively</i>
Pilot restraint system	<i>Lap belt used</i>
Co-pilot restraint system	
Escape time	

Información sobre el Operador

Operation type	<i>Non-Commercial Operations Pleasure Local</i>
Schedule type	<i>Non-scheduled</i>
Operator	<i>Argentina Private Operator</i>
Operator type	<i>Not applicable</i>



Líneas de Investigación

Descr factor subject	<i>Aircraft and operations Aircraft operation Flight crew use of procedures Landing site reconnaissance</i>
Factors justification	<i>ü Falta de planificación previa del vuelo y desconocimiento del aeródromo de destino</i>