



## Informe Preliminar

# Informe Preliminar

### Datos del Suceso

<b>File number</b>	13194494/22	
<b>Occurrence class</b>	<b>Accident</b>	
<b>Occurrence category</b>	RE: Runway excursion	
<b>Occurrence status</b>	Initial notification	
<b>UTC date/time</b>	10/2/2022	17:00
<b>State/area of occ</b>	South America Argentina	
<b>Location name</b>	Ad. Santa Teresita	
<b>Latitude of occ</b>	36:32:32 South	
<b>Longitude of occ</b>	56:43:17 West	

### Reseña del Vuelo

En un vuelo de aviación privado de recreación, durante la fase del aterrizaje la aeronave se fue de pista y capotó.

### Información del Vuelo

<b>Last departure point</b>	Argentina SAZL (SST) : Sta Teresita , Ba
<b>Planned destination</b>	Argentina SAZL (SST) : Sta Teresita , Ba
<b>Duration of flight</b>	0,2 Hour(s)
<b>Call sign</b>	
<b>Flight phase</b>	Landing



### Lesiones al Personal

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground						
Total on aircraft				1		1
Grand total				1		1

### Información de la Aeronave

<b>Aircraft registration</b>	<i>LV-HYE</i>
<b>State of registry</b>	<i>Argentina</i>
<b>Aircraft damage</b>	<i>Substantial</i>
<b>Manufacturer/model</b>	<i>DINFIA IA46 RANQUEL</i>
<b>Aircraft category</b>	<i>Fixed Wing Aeroplane Small Aeroplane Small Aeroplane</i>
<b>Year built</b>	
<b>Serial number</b>	<i>061</i>
<b>Maximum t/o mass</b>	
<b>Mass group</b>	<i>0-2 250 kg</i>
<b>Total cycles a/c</b>	
<b>Aircraft total time</b>	
<b>Maintenance docs</b>	
<b>Airworthiness cert.</b>	<i>Valid</i>

### Información del Motor

<b>Engine position</b>	<i>1</i>
<b>Manufacturer/model</b>	<i>LYCOMING 320 FAMILY</i>
<b>Engine serial number</b>	<i>L-11517-27</i>
<b>Time since new</b>	
<b>Engine cycles</b>	
<b>Time since overhaul</b>	



Cycles since overhaul

Time since inspection

#### Información de la Hélice

Prop position	1
Make of propeller	SENENICH PROPELLER MANUF.
Propeller model	M74DM
Prop serial	A33025
Time since new	
Time since overhaul	
Time since inspection	

#### Información sobre el Personal

Age		Gender	Male
Category	Pilot-in-command		
License type	Aeroplane pilot Commercial pilot		
License issued by	State of Registry		
Ratings	Rating not required		
Experience all a/c		Experience this a/c	
Experience all-90 days		Experience on a/c-90 d	
Experience all-24 hours		Experience on a/c-24 h	

#### Información Meteorológica

Weather relevant	Yes
Weather conditions	VMC
Visibility	
Light conditions	Daylight
Wind description	
Wind direction	
Wind speed	



Speed measured at

Wind gusts

#### Información sobre el Lugar del Suceso

**Wreckage location** *On aerodrome/airstrip*

**Terrain type** *Level/flat*

**Elevation terrain** *13 ft*

**Surface type** *Pavement*

**Length wreckage trail** *270 m*

**Rwy exit at** *Left side*

**Dist to exit**

#### Supervivencia

**Survivability** *Yes*

**Locating method** *Other*

**ELB-A, ELT status** *Not carried*

**Pilot restraint system** *Upper body restraint used*

**Co-pilot restraint system**

**Escape time**

#### Información sobre el Operador

**Operation type** *Non-Commercial Operations  
Pleasure  
Local*

**Schedule type** *Non-scheduled*

**Operator** *Argentina  
Other*

**Operator type** *Private owner*



#### Líneas de Investigación

**Descr factor subject** *Aerodrome generally*

**Factors justification** *Mantenimiento de las franjas de pista.*

#### Líneas de Investigación

**Descr factor subject** *Meteorological information  
Weather conditions  
Wind  
Crosswind*

**Factors justification** *Evaluación de la intensidad del viento cruzado durante el aterrizaje.*

#### Líneas de Investigación

**Descr factor subject** *Aircraft and operations  
Aircraft operation  
Cabin crew - actions*

**Factors justification** *El piloto no cumplía con experiencia reciente. No efectuó vuelos en cuatro meses. Su CMA no se encontraba vigente.*