



Informe Preliminar

Informe Preliminar

Datos del Suceso

| | | |
|----------------------------|--|-------|
| File number | 6496349/22 | |
| Occurrence class | Incident | |
| Occurrence category | BIRD: Birdstrike | |
| Occurrence status | Preliminary | |
| UTC date/time | 20/1/2022 | 09:45 |
| State/area of occ | South America Argentina | |
| Location name | Aeropuerto Internacional San Fernando (SADF) | |
| Latitude of occ | 34:27:18 South | |
| Longitude of occ | 58:35:29 West | |

Reseña del Vuelo

En un vuelo de aviación comercial no regular, posterior a la rotación, la tripulación sintió un ruido extraño acompañado de una guiñada de la aeronave y debido a los ruidos y vibraciones de la aeronave, la tripulación decidió regresar al aeropuerto.

Información del Vuelo

| | |
|-----------------------------|---|
| Last departure point | Argentina SADF : San Fernando, Ba |
| Planned destination | Argentina SAZS (BRC) : San Carlos De Bariloche, Rn |
| Duration of flight | 0,4 Hour(s) |



| | |
|---------------------|-----------------|
| Call sign | <i>LV-ZTR</i> |
| Flight phase | <i>Take-off</i> |

Lesiones al Personal

| | Fatal | Serious | Minor | None | Unknown | Total |
|--------------------------|--------------|----------------|--------------|-------------|----------------|--------------|
| Total on ground | | | | <i>0</i> | | <i>0</i> |
| Total on aircraft | | | | <i>2</i> | | <i>2</i> |
| Grand total | | | | <i>2</i> | | <i>2</i> |

Información de la Aeronave

| | |
|------------------------------|---|
| Aircraft registration | <i>LV-ZTR</i> |
| State of registry | <i>Argentina</i> |
| Aircraft damage | <i>Minor</i> |
| Manufacturer/model | <i>HAWKER HAWKER 800</i> |
| Aircraft category | <i>Fixed Wing Aeroplane Small Aeroplane</i> |
| Year built | <i>2000</i> |
| Serial number | <i>258462</i> |
| Maximum t/o mass | <i>12700 kg</i> |
| Mass group | <i>5 701 to 27 000 kg</i> |
| Total cycles a/c | <i>1471</i> |
| Aircraft total time | <i>2335 Hour(s)</i> |
| Maintenance docs | <i>Current</i> |
| Airworthiness cert. | <i>Valid</i> |



Información del Motor

| | |
|------------------------------|-------------------------------------|
| Engine position | 1 |
| Manufacturer/model | GARRET AIRESEARCH TFE 731 SERIES |
| Engine serial number | P-107468 |
| Time since new | 2335 Hour(s) |
| Engine cycles | 1471 |
| Time since overhaul | |
| Cycles since overhaul | |
| Time since inspection | |

Información del Motor

| | |
|------------------------------|-----------------------------|
| Engine position | 2 |
| Manufacturer/model | HONEYWELL GARRETT-TFE731 |
| Engine serial number | P-107460 |
| Time since new | 2335 Hour(s) |
| Engine cycles | 1471 |
| Time since overhaul | |
| Cycles since overhaul | |
| Time since inspection | |

Información sobre el Personal

| | | | |
|---------------------|-------------------------------------|---------------|------|
| Age | 59 Year(s) | Gender | Male |
| Category | Pilot-in-command | | |
| License type | Aeroplane pilot Commercial pilot | | |



| | | | |
|--------------------------------|-----------------------------|--------------------------------|--|
| License issued by | <i>State of Registry</i> | | |
| Ratings | <i>Held required rating</i> | | |
| Experience all a/c | | Experience this a/c | |
| Experience all-90 days | | Experience on a/c-90 da | |
| Experience all-24 hours | | Experience on a/c-24 ho | |

Información sobre el Personal

| | | | |
|--------------------------------|---|--------------------------------|-------------|
| Age | <i>60 Year(s)</i> | Gender | <i>Male</i> |
| Category | <i>Co-pilot</i> | | |
| License type | <i>Aeroplane pilot Commercial pilot</i> | | |
| License issued by | <i>State of Registry</i> | | |
| Ratings | <i>Held required rating</i> | | |
| Experience all a/c | | Experience this a/c | |
| Experience all-90 days | | Experience on a/c-90 da | |
| Experience all-24 hours | | Experience on a/c-24 ho | |

Información Meteorológica

| | |
|---------------------------|-----------------|
| Weather relevant | <i>No</i> |
| Weather conditions | <i>VMC</i> |
| Visibility | |
| Light conditions | <i>Daylight</i> |
| Wind description | |
| Wind direction | |
| Wind speed | |
| Speed measured at | |
| Wind gusts | |



Información sobre el Lugar del Suceso

| | |
|------------------------------|------------------------------|
| Wreckage location | <i>On aerodrome/airstrip</i> |
| Terrain type | <i>Level/flat</i> |
| Elevation terrain | <i>10 ft</i> |
| Surface type | <i>Pavement</i> |
| Length wreckage trail | |
| Rwy exit at | |
| Dist to exit | |

Información sobre el Operador

| | |
|-----------------------|---|
| Operation type | <i>Non-Commercial Operations Business</i> |
| Schedule type | <i>Non-scheduled</i> |
| Operator | <i>Argentina Other</i> |
| Operator type | <i>Corporate/executive</i> |

Líneas de Investigación

| | |
|------------------------------|---|
| Descr factor subject | <i>Aerodrome generally Aerodrome operations Wildlife control Bird control</i> |
| Factors justification | <i>Desempeño del aeródromo en la aplicación del control aviario</i> |



Líneas de Investigación

Descr factor subject

Aerodrome generally
Aerodrome procedures
Wildlife control procedures
Bird control procedures

Factors justification

Verificación de los procedimientos de control aviario del aeródromo